TEXAS OFFICIAL WOOD DESTROYING INSECT REPORT

Rule §7.176 Requires this department prescribed form to be used for real estate transactions in Texas regarding the visible presence or absence of wood destroying insects and conditions conducive to infestations of wood destroying insects.

	Plano	75023
Inspected Address	City	Zip Code

SCOPE OF INSPECTION

- A. This inspection covers only the multi-family structure, primary dwelling or place of business. Sheds, detached garages, lean-tos, fences, guest houses or any other structure will not be included in this inspection report unless specifically noted in Section 5 of this report.
- B. This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection. Examples of inaccessible areas include but are not limited to (1) areas concealed by wall coverings, furniture, equipment and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). Inspection does not cover any condition or damage which was not visible in or on the structure(s) at time of inspection but which may be revealed in the course of repair or replacement work.
- C. Due to the characteristics and behavior of various wood destroying insects, it may not always be possible to determine the presence of infestation without defacing or removing parts of the structure being inspected. Previous damage to trim, wall surface, etc., is frequently repaired prior to the inspection with putty, spackling, tape or other decorative devices. Damage that has been concealed or repaired may not be visible except by defacing the surface appearance. The WDI inspecting company cannot guarantee or determine that work performed by a previous pest control company, as indicated by visual evidence of previous treatment; has rendered the pest(s) inactive.
- D. If visible evidence of active or previous infestation of listed wood destroying insects is reported, it should be assumed that some degree of damage is present.
- E. If visible evidence is reported, it does not imply that damage should be repaired or replaced. Inspectors of the inspection company usually are not engineers or builders qualified to give an opinion regarding the degree of structural damage. Evaluation of damage and any corrective action should be performed by a qualified expert.
- F. THIS IS NOT A STRUCTURAL DAMAGE REPORT OR A WARRANTY AS TO THE ABSENCE OF WOOD DESTROYING INSECTS.
- G. If termite treatment (including pesticides, baits or other methods) has been recommended, the treating company must provide a diagram of the structure(s) inspected and proposed for treatment, label of pesticides to be used and complete details of warranty (if any). The warranty should specify which areas of the structure(s) are covered by warranty, renewal options and approval by a certified applicator in the termite category. Information regarding treatment and any warranties should be provided by the party contracting for such services to any prospective buyers of the property. The inspecting company has no duty to provide such information to any person other than the contracting party.
- H. There are a variety of termite control options offered by pest control companies. These options will vary in cost, efficacy, areas treated, warranties, treatment techniques and renewal options.
- I. There are some specific guidelines as to when it is appropriate for corrective treatment to be recommended.

 Corrective treatment may only be recommended if (1) there is visible evidence of an active infestation in or on the structure, (2) there is visible evidence of a previous infestation with no evidence of a prior treatment.
- J. If treatment is recommended based solely on the presence of conducive conditions, a preventive treatment or correction of conducive conditions may be recommended. The buyer and seller should be aware that there may be a variety of different strategies to correct the conducive condition(s). These corrective measures can vary greatly in cost and effectiveness and may or may not require the services of a licensed pest control operator. There may be instances where the inspector will recommend correction of the conducive conditions by either mechanical alteration or cultural changes. Mechanical alteration may be in some instances the most economical method to correct conducive conditions. If this inspection report recommends any type of treatment and you have any questions about this, you may contact the inspector involved, another licensed pest control operator for a second opinion, and/or the Structural Pest Control Service of the Texas Department of Agriculture.

SPCS/T-5 (Rev. 9/1/2020) Page 1 of 4

	Plano			75023		
Inspected Address	City				Zip Co	de
1AName of Inspection Company	1B	SPC	S Business Lice	anse Number		
Name of inspection company	D. II					
1CAddress of Inspection Company	Dallas City	TX Stat		75206 Zip	Te	lephone No.
Drive Wheeter # 0040007, 044,000,0000 houlest	on@brickkicker.com	4.5	···	·	_	•
Name of Inspector (Please Print)	OT @ DTCKNICKCT.COTT		ified Applicator nnician		☐ (ch	eck one)
	1F					
	Inspection	n Date				
2Name of Person Purchasing Inspection		_Seller	t 🗌 Buyer 🛚	Managemen	t Co. Other	
3N/A		<u> </u>				
Owner/Seller 4.REPORT FORWARDED TO: Title Company or Mortgagee (Under the Structural Pest Control regulations only the			er □ eive a copy)	Agent 🛚	Bu	yer 🛚
The structure(s) listed below were inspected in accordance with	the official inspection proce	dures adopted by	the Texas Depa	artment of Ag	riculture Structu	ral Pest Control Service
This report is made subject to the conditions listed under the Sco	ppe of Inspection. A diagram	m must be attach	ed including all s	structures insp	ected.	
5A. List structure(s) inspected that may include residence, detached	Single Family F	Residence	/Defeate Dest	A Coope of I	nanastian)	
	garages and other structure	es on the property	/. (Refer to Part	A, Scope of I	nspection)	
5B. Type of Construction: Foundation: Slab ☑ Pier & Beam ☐ Pier Type: N.	Basement 🗆 C	Other:N/A	N/A			
Siding: Wood ☐ Fiber Cement Board ☐ Brick ☒ Stone ☐ Roof: Composition ☒ Wood Shingle ☐ Metal ☐ Tile ☐	Other:					
6A.This company has treated or is treating the structure for the fo				N/A	0	
If treating for subterranean termites, the treatment was: If treating for drywood termites or related insects, the treatment ν		Spot Limited	Bait		Other	
6B. N/A		N/A			N/A	
Date of Treatment by Inspecting Company	Comm	on Name of Insec	et	Name of	f Pesticide, Bait	or Other Method
This company has a contract or warranty in effect for control of the		ng insects:	Termi	to.		
Yes ☒ No ☐ List In: If "Yes", copy(ies) of warranty and treatment diag			Tellili	ile .		
Neither I nor the company for which I am acting have had, prese	ntly have, or contemplate h	aving any interes	in the purchase	e or sale of thi	s property. I do	further state that neithe
I nor the company for which I am acting is associated in any way Signatures:	,,,,	estate transaction				
7A. // / / / / / / / Inspector (Technician or Certified Applicator Name and Licens	# 0816687 e Number)					
Others Present:						
7B		. ,,				
Apprentices, Technicians, or Certified Applicators Name(s) and	I Registration/License Num	iber(s)				
Notice of Inspection Was Posted At or Near: 8A. Electric Breaker Box 8B.	Date Posted:	12/15/2020				
Water Heater Closet ☐ Beneath the Kitchen Sink ☒						
9A.Were any areas of the property obstructed or inaccessible?	Yes	X	No	Е		
(Refer to Part B & C, Scope of Inspection) If "Yes" specify in 9B.		^	NO	ı		
9B.The obstructed or inaccessible areas include but are not limit Attic Insulated area of a		Areas 💟	Plantor k	ooy abutting s	tructuro 🗆	
Deck Sub Floors	☐ Slab Joint		Crawl Sp			
Soil Grade Too High		Ц	Weepho N/A	iles		
10A.Conditions conducive to wood destroying insect infestation: (Refer to Part J, Scope of Inspection) If "Yes" specify in 10B.	Yes		No			
10B.Conducive Conditions include but are not limited to: Wood to Groun	d Contact (G)	☐ Formboar	ds left in place (I)	cessive Moisture	e (J) 🔲
Debris under or around structure (K) Footing too low	or soil line too high (L) ontact with Structure (Q)	Wood Rot Wood Rot		´ ☐ He	avy Foliage (N)	
Insufficient ventilation (T)	Specify:			V/A	. ,	
-						
	and Regulated by the Te					
PO Box 12847, A	ustin, Texas 78711-2847	Phone 866-918-4	481, Fax 888-2	32-2567		

SPCS/T-5 (Rev. 9/1/2020)

	Plano	75023
Inspected Address 11. Inspection Reveals Visible Evidence in or on the structure: 11A.Subterranean Termites 11B.Drywood Termites 11C Formosan Termites 11D.Carpenter Ants 11E.Other Wood Destroying Insects Specify: N/A	Yes No X Yes	Zip Code
11F.Explanation of signs of previous treatment (including pesticic	es, baits, existing treatment stickers or other methods) i	pentified: N/A
11G.Visible evidence of: N/A	has been observed in the following area	ıs: N/A
If there is visible evidence of active or previous infestation, it mus inspected must be noted in the second blank. (Refer to Part D, E 12A. Corrective treatment recommended for active infestation of Scope of Inspection) 12B. A preventive treatment and/or correction of conducive condictive Specify reason: Footing too low or soil line too high (L), Refer to Scope of Inspection Part J	& F, Scope of Inspection) evidence of previous infestation with no prior treatmer Yes □ No ☑ tions as identified in 10A & 10B is recommended as follo	t as identified in Section 11. (Refer to Part G, H, and lows: Yes ⊠ No □
The inspector must draw a diagram including approximate perime Evidence of Infestation, A-Active; P-Previous; D-Drywood Termite Carpenter Ants; Other(s) – Specify	es; S-Subterranean Termites; F-Formosan Termites; C-C	
78 Conduce Conditions include Detris under or around structure (Patiet box abding structure (o) Issufficier verification (1) The inspector must drave a diagram Evidence of infestion, Authoric, Carpeter Arts, (Oher(s) – Specific Conductive Conditions which makes it eligible for WDI St	windowsill and at from the contact of the contact o	to for They did not be carpenter ecommend and keeping grants and structure. 4-6 inches er to prevent mentry. it stations do not the of house. The following codes: E-ring Beefles: H-

SPCS/T-5 (Rev. 9/1/2020) Page 3 of 4

		Plano	75023
Inspected Address	City		Zip Code
	Stateme	nt of Purchaser	
have received the original or a legible copy of this form. understand that my inspector may provide additional inf	I have read and understand	any recommendations made. I ha	ave also read and understand the "Scope of Inspection."
f additional information is attached, list number of pages		1	
Signature of Purchaser of Property or their Designee		Date	
	Buyer's Initials		
a Customer of Designee Not Fresent	Buyer 3 miliai3		

SPCS/T-5 (Rev. 9/1/2020) Page 4 of 4



